



Inventory number: 22674

Measuring machine
WERTH Scope Check V
2010



Technical data

Max. measuring length	500 mm
Max. diameter with	160
Maximum workpiece weight	15 kg
Air connect	7 bar
Machine's weight about	1500 kg
Overall dimensions machine:	
Length	1000 mm
Width	1000 mm
Height	2000 mm



















Cleaning the Fibers

The fibers should be cleaned only with the supplied cleaning agent. The fiber insert should always be cleaned before the measuring process starts and after an exchange. To clean the fiber, a special stick with conical tip is moistened with the cleaning agent and wiped carefully from the middle of the fiber to the end (tip). The order number of the cleaning kit is 95.0693.0067.

Attention: The upper part of the fiber probe is extremely fragile! The cleaning agent can only be used 4 month, after this period the cleaner might be inapplicable due to chemical reaction.

Please keep dark and in a cool place!

Attention: To remove the fiber, please press the plastic bar in the direction of the arrow, to take the fiber out from above without any bending.

blue mark=Titan Fiber

